From: Michael A Glagola (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC0210] 1/25/2016 2:49:37 PM Sent: To: Doug Wight (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Dougla7]; John A Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JOHN171d28]; Michael J Winters (Generation -34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082] FW: Possum Toe Drain Separation Drawing Subject: Attachments: C150132-00-054-C-A2-001-SKETCH-FIGURE 1.pdf **FYI** From: John Klamut [mailto:J.Klamut@gaiconsultants.com] **Sent:** Monday, January 25, 2016 1:54 PM **To:** John Glover; rwilliams@gloverconstruction.com Cc: Scott Quinlan; Brian Bullock; Michael A Glagola (Generation - 34); John DeBarbieri Subject: Possum Toe Drain Separation Drawing John/Reuben, This is our working drawing for the toe drain separation. We will be sending this to DEQ, please review and provide any edits or comments, we want to be sure what we send them is correct. Give me a call with any questions. Thanks, John John R. Klamut, P.E. **Engineering Manager** GAI Consultants, Inc.

4200 Triangle Lane, Export, PA 15632-1358



transforming ideas into reality, since 1958 | gaiconsultants.com

CONFIDENTIALITY NOTICE: This communication contains confidential information belonging to the sender and may be legally privileged. This communication is solely for the use of its intended recipient. If you are not the intended recipient, inform the sender of the error and remove this email from your system. If this transmission includes any technical information, design data, and/or recommendations, they are provided only as a matter of convenience and may not be used for final design and/or construction.